



Service

- If you publicers, please contact with the regard attent, the calibrate service track will interview your mentions, along the product using and other afer alles burgh.
- other associations in the sponse of by the first year of particular 2. Workship is in the sponse of by the first year is not included 3. Plane is near the web year with existing a set samphows A pleasa to be easily present a height for us to make the preparities failing providing years is better product superiorest

Product Parameters EN .

KN Muslimi Tarlya Alf Versiaan, KEA Hayley Capacity Banker's Utiliaovide Bill Fridgenrey Rengin 2, 400 E 4000rej Auda Despanney, 2019 (2019) Onlives Sale (2019) Onlives Sale (2019) Transmission Nation III Sale (2019) Transmission Nation III Banwith (1), 1124902, 2014 Diag Tome, Alexan II Hours Elarphone's Diagong Tome Adapt Linear

71

VT Nodelin Delta Minish Haritanih VKLS Devido de Licenzia for Capacitario de America Bio ACUITINANA Propuères de Pouperania J. 400 - 4400 es Negulio anto Autor. Delta 2010 Alta-Nalema Hillion Manhaime Hillion Manazario de Tropperando 2010 Manazario de Tropperando 2010 Demailio dante 11200 f. 1680 Demailio dante 11200 f. 1680

110

Hallis Data H'Innan Variate IV Lapacia da La Dateau Mitchill (2011) Februario de la Dateau Mitchill (2011) Februario de l'antenno 1 4001 (400) Februario de l'antenno 1 4001 (400) Februario de la Dateau Had parket 813744 registerer (812±15%) Polite de Tanoressen (849 Serept Ar Jacobert (1849) Terept Ar Jacobert (1840) Terept Ar Jacobert (1840) Terept an Overer (1840)

产品合格证 产品发生 Product Highel Printed Type skerker Geschiert 0,000,000,0000 matrial Impediati Q.C. persond D1 放驶合格 0.81% 11-04-20-ACOUNT M 448 Protection 443 Links Protection Protection Research Control Research Control Research Control Research Control Research Control Research Resear Antonio Biologia Constraint Const man freite.

21日本中 11日本中	 Эликулария Эликулария	 AR Mangai Darkis, and importance WAB, and importance WAB, and importance WAB and and "XVW/Webbalters in the X-2412 2 AM (Specific version and the WAB) application in the X-2412 2 AM (Specific version and the WAB) and the X-212 and the Specific version and the WAB (Specific version and the WAB) and the X-212 and X-2000 (Specific Version and the WAB) and the Y-WAB (SWEAP) (XVM) and the WAB) and the WAB) (XVM) (XVM) and the WAB) (XVM) (XVM) (XVM) and the WAB) (XVM) (XVM) and the WAB) (XVM) (XVM) (XVM) (XVM) (XVM) and the WAB) (XVM) (XVM) (XVM) (XVM) (XVM) and the WAB) (XVM) (XV	<section-header><section-header><section-header><section-header><section-header><section-header><text><text><text><text><text><text><text><text><text><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></text></text></text></text></text></text></text></text></text></section-header></section-header></section-header></section-header></section-header></section-header>
	-		

FCC Statement

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1)This device may not cause harmful interference.(2)This device must accept any interference received, including interference that may cause undesired operation.

2. Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment. Note: This equipment has been tested and found to comply with the limits for a class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates uses and can radiate radio frequence energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation if this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

Reorient or relocate the receiving antenna.

Increase the separation between the equipment and receiver.

Connect the equipment into an autlet on a circuit different from that to which the receiver is connected.

Consult the dealer or an experienced radio/TV technician for help.