

1. Please note that as this is a licensed device and not a part 15 device the proper test method is TIA603 as applicable. The report states ANSI C63.4 was used as a test method. Please note that ANSI C63.4 is not a proper test method for licensed devices. The only test which would use ANSI C63.4 would be the receiver spurious emissions verification under Part 15. However, this test is not part of the report. Please explain why this improper test method is listed? Please list the proper test methods used for antenna substitution measurements.

We confirm, that substitution measurement method was used for EIRP and spurious emission measurements. The EIA/TIA-603-A has been added as reference to the revised test report.

2. Please note that test reports are to reflect the actual conditions during the test sequence. Please note that on page 12 (section 3.4.1) you state that "The excess length of the cables of the EUT were made into bundles 30-40 cm in length." Please note that the setup photos show that there are no cables with the device. Please report the actual conditions during testing. Please remove 'canned text' report items that do not apply.

The note was left in the report by accident, it has been corrected in the revised test report.

3. Please provide the calibration dates for equipment used in the EMC report.

The calibration dates are stored in a register, from which the values would need to be picked manually one by one. It is the laboratory's policy, that all test equipment are calibrated once a period, which is stated in the section containing the list of test equipment. Uncalibrated equipment are not used for the measurements. See the revised test report.