

APPENDIX C: CHANGE DOCUMENT

Please refer to the following pages.



Sony Ericsson

Prepared by
SEM/BMDH JEAN-PHILIPPE LAMANTIA
Contents responsible if other than preparer

Approved by

Confidential
RELEASE NOTES

Document number
1/109 47-LXE 108 566 Uen

Date
2004-02-02

Remarks
This document is managed in metaDoc.

1(3)

Revision
PA2

CM-42 Hardware Release Notes



Prepared by
SEM/BMDH JEAN-PHILIPPE LAMANTIA
Contents responsible if other than preparer

Approved by

1 Overview

1.1 Description

This document is intended to summarize the changes made to the Printed Circuit Board (PCB) of the CM-42 product.

1.2 Document Revision History

Revision	Date	Comments
PA1	02-Feb-2004	Initial version
PA2	02-Feb-2004	Updated layout changes

1.3 PCB Information

The PCB is identified by a TVK number and revision.

PCB Info	
CM-42	TVK1172419
Current Revision	R5

Revision Change	Driving reason(s)
R4 to R5	New VCTCXO form factor and add antenna diagnostic capability.



Prepared by
SEM/BMDH JEAN-PHILIPPE LAMANTIA
Contents responsible if other than preparer

Approved by

2 Board Details

2.1 R5 changes from R4 board

Layout Changes

- Form factor of current VCTCXO will no longer be available after 12/31/2003. Change over required to accommodate change in the new VCTCXO footprint. Replaced VCTCXO with newer, smaller package.
- Updated 800 Mhz duplexer footprint and heatsink area.
- Added antenna diagnostics capability.
- Removed unused PCS band LNA.
- Removed unused PCS band amplifier.
- Removed unused 800 MHz filter.
- Modified receiver ground plane in an attempt to improve sensitivity.
- Removed unused RF connector pads to allow for a blind alignment slot.

Component Changes

- Increased Flash Memory capacity.
- Changed R703 from 22k Ω to 220k Ω to stabilize the Host Power B circuitry over temperature.
- Changed R705 from 1k Ω to 220k Ω to reduce inrush current.