



56043255XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3423/1

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

FCC ID: NT8UCON2

IC: 3043A-UCON2



VS9832C000YA

VISTEON CORPORATION

DRS

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:

k:\PLUS\11830-05PA\electronics\engineering\parts record.xls

Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

05PA
4.8.0#9
J1050
Plain



05091004XX



DAIMLERCHRYSLER PCL: TBD
PROD. DATE/SHIFT: 3423/1
MAIN S/W REV: 4.8.0 H/W REV: 000A 75813
FCC ID: TBD
IC: TBD



VS9830C003ZA



!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:
K:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.



05064013XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3283/2

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

BUS S/W REV: 1.0

FCC ID: NT8UCON2



IC: 3043A-UCON2

VS8734C0014A

VISTEON CORPORATION

CHN

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:
K:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.