




# 12.5.2. Test Graphs

























# REPORT NO.: 4790194584 -4 Page 440 of 497






# REPORT NO.: 4790194584 -4 Page 441 of 497






# REPORT NO.: 4790194584 -4 Page 442 of 497






# REPORT NO.: 4790194584 -4 Page 443 of 497






# REPORT NO.: 4790194584 -4 Page 444 of 497






# REPORT NO.: 4790194584 -4 Page 445 of 497






# REPORT NO.: 4790194584 -4 Page 446 of 497






# REPORT NO.: 4790194584 -4 Page 447 of 497






# REPORT NO.: 4790194584 -4 Page 448 of 497






# REPORT NO.: 4790194584 -4 Page 449 of 497











# REPORT NO.: 4790194584 -4 Page 451 of 497






# REPORT NO.: 4790194584 -4 Page 452 of 497






# REPORT NO.: 4790194584 -4 Page 453 of 497






# REPORT NO.: 4790194584 -4 Page 454 of 497






# REPORT NO.: 4790194584 -4 Page 455 of 497






# REPORT NO.: 4790194584 -4 Page 456 of 497






# REPORT NO.: 4790194584 -4 Page 457 of 497






# REPORT NO.: 4790194584 -4 Page 458 of 497






# REPORT NO.: 4790194584 -4 Page 459 of 497






# REPORT NO.: 4790194584 -4 Page 460 of 497





# REPORT NO.: 4790194584 -4 Page 461 of 497




UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



# REPORT NO.: 4790194584 -4 Page 462 of 497












# REPORT NO.: 4790194584 -4 Page 464 of 497













# REPORT NO.: 4790194584 -4 Page 467 of 497

