

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 2. Bottom of EUT

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 3. Side 1 and Front

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 4. Side 2, Battery Side, and Front

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976




Figure 5. Battery Side with Battery Pack Removed

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 6. Battery side with Battery Pack Installed

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 7.Back, Electrode Side

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 8. Battery Packs