

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976

INTERNAL PHOTOGRAPHS




Figure 1. Side 1 (Processor Board and LED)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976




Figure 2. Side 2 (Trace Antenna Board)

Note: Trace Antenna runs along the perimeter of the PCB as pointed by the red arrows.

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976




Figure 3. Side 3 (Buzzer)

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 4. Inside Battery Compartment

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976



Figure 5. Top Side, Component Side

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976




Figure 6. Side 1, Shield Removed

Part 95J
KE3-3003170
18-0013
March 9, 2018
Radio Systems Corp
RIF00-15976

