Report No: 16061329HKG-001

## **Configuration Photographs**

## **Worst-Case Radiated Emissions**

(Front View)

Model: 0805



Report No: 16061329HKG-001

## **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Back View)

Model: 0805



Report No: 16061329HKG-001

## **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Front View)

Model: 0805




Report No: 16061329HKG-001

# **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Back View)

Model: 0805




Report No: 16061329HKG-001

## Configuration Photographs

#### **Worst-Case Radiated Emissions**

(Front View)

Model: **0805** 




Report No: 16061329HKG-001

# **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Back View)

Model: **0805** 



Report No: 16061329HKG-001

## **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Front View)

Model: 0805




Report No: 16061329HKG-001

# **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Back View)

Model: **0805** 




Report No: 16061329HKG-001

## Configuration Photographs

#### **Worst-Case Radiated Emissions**

(Front View)

Model: 0805



Report No: 16061329HKG-001

# **Configuration Photographs**

#### **Worst-Case Radiated Emissions**

(Back View)

Model: **0805** 

