



December 10, 2014

Timco Engineering Inc.
849 NW State Road 45
Newberry, FL 32669

SUBJECT: Error in Report for ACUITY BRANDS LIGHTING, INC - FCC ID:
2ADCBFCS7TSN - JOB #: 1978UC14 and IC: 6715C-FCS7TSN - JOB #:
1978IC14

Dear Timco,

It has come to our attention that the test report for the FCC and IC Certification for the product referenced above cites the incorrect type of antenna used by the radio module. The originally submitted test report cited a trace antenna when, in fact, the radio uses a chip antenna.

We have uploaded a corrected report and respectfully ask that you notify the FCC and Industry Canada of the correction made to Page 17, Table 4, and have the previously submitted test report superseded by this corrected version.

Sincerely,

A handwritten signature in dark ink, appearing to read 'Sandi McEnery', is written over a light blue horizontal line.

Sandi McEnery
Agent