



March 25, 2015

Federal Communication Commission  
Office of Engineering and Technology  
USA

RE: FCC ID:NEODMBA30073008PS  
Form 731 CN: EA213707  
Subject: CRN 46732

Dear Mr. Harrington,

Please find attached our response according to your question.

1. 4-bis) Install/operate manual at pdf pg 6 includes:

"gain of the signal booster should be set so that the EIRP of the output noise from the signal booster should not exceed the level of -43 dBm in 10 kHz"

That does not match FCC rules, please revise; i.e. please change from "EIRP" to "ERP."

**Response:** [The revised User\\_manual\\_25633A\\_rev2](#) uploaded on March 25, 2015.

Sincerely yours,

A handwritten signature in blue ink, appearing to be "Raviv Cohen".

Raviv Cohen, R&D Engineer  
Axell Wireless Israel Ltd.

A handwritten signature in black ink, appearing to be "M. Nikishin".

M. Nikishin, EMC and Radio group manager  
Hermon Laboratories Ltd.