

Response for MCLABALONE200

1. Photo has been updated and re-uploaded.
2. the same as item 1
3. they are connected by flexible cable and a connector, they are shown in the original photos, pls double check.
4. it has 3 pages in this file, it does include the part list for the boards (reply from client).
5. updated
6. updated
7. changing channel bandwidth to channel spacing
8. has been uploaded as a separate file
9. has been uploaded as a separate file
10. crest factor 8.3 is correct. The phone has no GPRS function. The operational description has been updated.