DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



Appendix B: Photographs




Figure B.1: DUT front view




Figure B.2: DUT rear view





Figure B.3: DUT side view




Figure B.4: DUT rear view






Figure B.5: DUT with accessories






Figure B.6: Radiated Test setup 1




Figure B.7: Radiated Test setup 2