

Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)






Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)







Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)







Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)







Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)






Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)






Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)







Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)






Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)





Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)





Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)





Report No.: 16070293HKG-003 (FCC) 16070293HKG-004 (IC)

Equipment Photographs

Model: 0442

(Internal)



