

5395 Pearl Parkway, Suite 100 Boulder, CO 80301 303.444.3862 www.freewaye.com

Date: 06/01/2018

Federal Communications Commission Authorization & Evaluation Division 7345 Oakland Mills Road Columbia, Maryland 21046

RE: Difference Between Rev. B and Rev. C boards for FCC ID: KNYPMT0101AB, Granted 06/30/2016

To Whom It May Concern:

We, FreeWave, are submitting an application to fix internal pictures submitted against FCC ID: KNYPMT0101AB. Following are the changes between Rev. B and Rev. C boards.

- Rev C primarily added a saw filter F1 to the transmit path. L2 and C6, were added to the layout near the saw filter, but they are DNI and 0 Ohm and have no electrical function other than providing flexibility if needed.
- L3 was added to the transmit output filter (and the values of C45 and C51 were changed) to improve harmonic suppression.
- The inductor L1 was changed from a wire-wound to multi-layer inductor. This inductor is used on the DC-DC buck regulator within the CC13x0 chip.
- C65 and C67 are capacitors that were added to the RF power detector outputs to smooth the detector level when sampled by the ADC's
- The supply rail to the PA was increased from 3.8 to 4.0V, and the value of C63 (bulk decoupling on the PA supply rail) was increased 0.1uF->10uF to reduce transient voltage dips.
- Rev B used CC1350 or CC1310 interchangeably, while the BOM for Rev C uses CC1310 exclusively.



5395 Pearl Parkway, Suite 100 Boulder, CO 80301 303.444.3862 www.freewave.com

Please contact me if you have any questions or need further information regarding this application.

Sincerely,

Riaz Momand

Sr. Compliance Engineer FreeWave Technologies, Inc.