


**PICTURES OF THE UNIT UNDER TEST  
&  
THE TEST SETUP**

**Section 2.1093(c)** Photo of the test setup shall be provided.

Testing was done at Rhein Tech laboratory in Herndon, VA, USA.

PHOTO 1: RADIATED EMISSIONS, NO TERMINATING CABLE - DUT




**PICTURES OF THE UNIT UNDER TEST  
&  
THE TEST SETUP  
CONT.**

PHOTO 2: RADIATED EMISSIONS, NO TERMINATING CABLE - DUT



**PICTURES OF THE UNIT UNDER TEST  
&  
THE TEST SETUP  
CONT.**

PHOTO 3: RADIATED EMISSIONS, NO TERMINATING CABLE - TEST SITE







**PICTURES OF THE UNIT UNDER TEST  
&  
THE TEST SETUP  
CONT.**

PHOTO 2: RADIATED EMISSIONS, WITH TERMINATING CABLE - DUT



**PICTURES OF THE UNIT UNDER TEST  
&  
THE TEST SETUP  
CONT.**

PHOTO 3: RADIATED EMISSIONS, WITH TERMINATING CABLE - TEST SITE

