

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H


Page 84 of 105






Component Side of ETR with Shields Installed PCB (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 85 of 105




Component Side of ETR PCB without Shields Installed (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 86 of 105



Opposite Side of ETR PCB (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 87 of 105




Component Side of DCM with Shields Installed PCB (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 88 of 105



Component Side of DCM PCB without Shields Installed (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 89 of 105



Opposite Side of DCM PCB (Base)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 90 of 105



Component Side of PCB with LCD Display (Handset)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 91 of 105




Component Side of PCB without LCD Display (Handset)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 92 of 105



Opposite Side of PCB with Shield Installed (Handset)

TEST REPORT: 73-6951 FCC ID: AS5LITMDW9H Page 93 of 105



Opposite Side of PCB without Shield Installed (Handset)