DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



Appendix B: Photographs

Report No: 4007ERM.001 08-23-2023






Figure B1: Front View of Conducted sample




Figure B2: Rear View of Conducted sample





Figure B3. Front View of Radiated sample




Figure B4. Front View of DUT with Accessories






Figure B5. Low Range Radiated Emission test setup



Figure B6. High Range Radiated Emission test setup 1





Figure B7. High Range Radiated Emission test setup 2