

NCXC"KpvtpevkpciNko kgf ""
Cfftguu<C/78."Ugewt/86."I cwco "Dwffj c"P ci ct."P qkf c.Wwct'Rtcf guj ."Kpf kc
Vgn<- ; 3/; 8766: 32: 2"
Hcz<- 2342/6859462""
Go cln<rzkk0ij cto cB rxcclpvtpevkpci0p

F cvg<4246/2: /23

HGF GTCN'EQO O WP KECVKQP U'EQO O KUUKQP U"

Cwj qtk cvkqp"cpf "Gxcnwcvkqp"F kxkukqp"

9657"Qcmrpf "O kmu"Tqcf "

Eqnwo dlc."O F "43268"

F gct"Uk IO cf co ."

Qwt"rtqf wev"Vcdrgv."o qf gn<U: 3."U: 3C."U: 3S."U: 3Z"."U: 3R."U: 3\ , FCC ID: 2ARTX-S81,
for marketing purpose,this product only supports GSM:850/1900;WCDMA:Band5;
LTE:Band5/7/38/41(band41:2555-2655MHz), Bluetooth, BLE 1M/2M;
2.4GWi-Fi (2412-2462 MHz); 5G Wi-Fi (5150-5250MHz, 5250-5350MHz, 5470-5725MHz,
5725-5850MHz); The other functions, bands were disabled by the software, the end user has
no capability to activate it.

Sincerely Yours,



Signature:

Printed Name: Laxit Sharma

Title: Manager