

C18 charges to a much higher voltage when uC maintains power line than when the counter causes tag to power up (due to instant Reset pulse in the latter case). The difference is worse for small-hysteresis gates, such as Rohm's.

