


7. Photographs of the Test Set-Up


Photograph 1: Set-up for Spurious Emissions (Front View 1)




Photograph 2: Set-up for Spurious Emissions (Front View 2)




Photograph 3: Set-up for Spurious Emissions (Back View 1)




Photograph 4: Set-up for Spurious Emissions (Back View 2)



Photograph 5: Set-up for Spurious Emissions (Back View 3)



Photograph 6: Set-up for Spurious Emissions (Back View 4)




Prüfbericht - Nr.: 50287839 001
Test Report No.

Seite 45 von 47
Page 45 of 47

Photograph 7: Set-up for Conducted testing (View 1)



Photograph 8: Set-up for Conducted testing (View 2)



Prüfbericht - Nr.: 50287839 001
Test Report No.

Seite 46 von 47
Page 46 of 47

Photograph 9: Set-up for Mains Conducted testing (Back View)



Photograph 10: Set-up for Mains Conducted testing (Front View)

