



Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
Phone: 408-526-4000  
Fax: 408-526-4100  
<http://www.cisco.com>

**Tune-up Procedure**

Date: June 13, 2017

Subject: FCC ID: LDK60241556

The RF module and hardware PCB is designed to meet FCC requirements. The maximal output power for all transceivers is fixed by firmware and cannot be changed by the user either through software upgrades or any other means.

Sincerely,

By:

  
(Signature/Title)

\_\_\_\_\_  
(Print name)

Torbjorn Sundsvalen