

FccID: H9PNP4046

Conf Num: EA99556

Correspondence # 19611

DS NetVision® Phone

Original Equip.

Date Emailed: 6/13/01

Question 1

The request for change in FCC identifier must be submitted in the filing.

Answer:

Please change the FCC identifier from H9PDM4046 to H9PNP4046.

Question 2

The label must be corrected and submitted.

Answer:

Please see the uploaded corrected label.

Question 3

The the SAR report lists the "Stick on" antenna as 0 dBi while the latest exhibit lists it as 2 dBi.

Answer:

The SAR report is incorrect. The correct gain for the "Stick on" antenna is 2 dBi.

Question 4

Indicate whether the device transmits simultaneously on both antennas when the "Stick on" antenna is installed.

Answer:

The device only transmits on one antenna at a time.

Question 5

The RF safety needs revision. Remove the word Warning. Since SAR was tested, revise the statements to include only the following To comply with RF safety requirements use the specific belt clip. All other belt clips should be avoided and may not comply with RF safety requirements.

Answer:

Please see the uploaded revised Regulatory Addendum.