

2022-01-10

updated: (3) controls, (4.2) reset, P.11 Arabic RF power

[illegible]