











ANT L_802.11ax_HE40_26T_Low_UNII 1



ANT L_802.11ax_HE40_26T_Low_UNII 2A





ANT L_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-01326
Page (271) / (539) Pages





ANT L_802.11ax_HE40_26T_Low_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





Report No.:
CTK-2023-01326
Page (272) / (539) Pages



ANT R_802.11ax_HE40_26T_Low_UNII 1



ANT R_802.11ax_HE40_26T_Low_UNII 2A





ANT R_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (273) / (539) Pages







ANT R_802.11ax_HE40_26T_Low_UNII 3



ANT L_802.11ax_HE40_26T_Mid_UNII 1



ANT L_802.11ax_HE40_26T_Mid_UNII 2A




ANT L_802.11ax_HE40_26T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (275) / (539) Pages







ANT L_802.11ax_HE40_26T_Mid_UNII 3



ANT R_802.11ax_HE40_26T_Mid_UNII 1



ANT R_802.11ax_HE40_26T_Mid_UNII 2A





ANT R_802.11ax_HE40_26T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (277) / (539) Pages







ANT R_802.11ax_HE40_26T_Mid_UNII 3



ANT L_802.11ax_HE40_26T_High_UNII 1



ANT L_802.11ax_HE40_26T_High_UNII 2A





ANT L_802.11ax_HE40_26T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (279) / (539) Pages





ANT L_802.11ax_HE40_26T_High_UNII 3



ANT R_802.11ax_HE40_26T_High_UNII 1



ANT R_802.11ax_HE40_26T_High_UNII 2A





ANT R_802.11ax_HE40_26T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (281) / (539) Pages







ANT R_802.11ax_HE40_26T_High_UNII 3



ANT L_802.11ax_HE40_52T_Low_UNII 1



ANT L_802.11ax_HE40_52T_Low_UNII 2A





ANT L_802.11ax_HE40_52T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-01326
Page (283) / (539) Pages





ANT L_802.11ax_HE40_52T_Low_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





Report No.:
CTK-2023-01326
Page (284) / (539) Pages



ANT R_802.11ax_HE40_52T_Low_UNII 1



ANT R_802.11ax_HE40_52T_Low_UNII 2A





ANT R_802.11ax_HE40_52T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (285) / (539) Pages







ANT R_802.11ax_HE40_52T_Low_UNII 3



ANT L_802.11ax_HE40_52T_Mid_UNII 1



ANT L_802.11ax_HE40_52T_Mid_UNII 2A





ANT L_802.11ax_HE40_52T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (287) / (539) Pages







ANT L_802.11ax_HE40_52T_Mid_UNII 3



ANT R_802.11ax_HE40_52T_Mid_UNII 1



ANT R_802.11ax_HE40_52T_Mid_UNII 2A





ANT R_802.11ax_HE40_52T_Mid_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (289) / (539) Pages







ANT R_802.11ax_HE40_52T_Mid_UNII 3



ANT L_802.11ax_HE40_52T_High_UNII 1



ANT L_802.11ax_HE40_52T_High_UNII 2A





ANT L_802.11ax_HE40_52T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (291) / (539) Pages







ANT L_802.11ax_HE40_52T_High_UNII 3



ANT R_802.11ax_HE40_52T_High_UNII 1



ANT R_802.11ax_HE40_52T_High_UNII 2A





ANT R_802.11ax_HE40_52T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (293) / (539) Pages







ANT R_802.11ax_HE40_52T_High_UNII 3



ANT L_802.11ax_HE40_106T_Low_UNII 1



ANT L_802.11ax_HE40_106T_Low_UNII 2A





ANT L_802.11ax_HE40_106T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (295) / (539) Pages







ANT L_802.11ax_HE40_106T_Low_UNII 3



ANT R_802.11ax_HE40_106T_Low_UNII 1



ANT R_802.11ax_HE40_106T_Low_UNII 2A





ANT R_802.11ax_HE40_106T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (297) / (539) Pages







ANT R_802.11ax_HE40_106T_Low_UNII 3



ANT L_802.11ax_HE40_106T_Mid_UNII 1



ANT L_802.11ax_HE40_106T_Mid_UNII 2A





ANT L_802.11ax_HE40_106T_Mid_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-01326
Page (299) / (539) Pages



ANT L_802.11ax_HE40_106T_Mid_UNII 3