



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 15, 2002

RE: FCC ID: AB6NT800MFRM2
Attention: Thomas Wong

I have a few comments on this Application.

- 1 On page 12 of 68 in the Samnina Test report the set up drawing shows that a splitter was used to allow both a Power Meter and a Spectrum Analyzer to be connected to the device. This parallel path has the potential of causing erroneous readings due to a possible impedance mismatch conditions. What steps were taken to insure that any variation in readings was correctly accounted for due to this setup?
- 2 Please provide the manual for the application. If confidentiality is desired for the manual, please provide a revised request for confidentiality specifically mentioning the manual along with all other confidential items.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.