



American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

July 1, 2002

RE: FCC ID: D6XBT3033

Attention: JT Chen

I have a few comments on this Application.

- 1 Calibration of the ESCS30 Receiver is out of date (see page 8 of the test report). Please provide test data with calibrated equipment.
- 2 In the 20dB bandwidth test the report states that the hopping function was enabled. In order to perform an appropriate 20dB bandwidth test the hopping function must be turned off. This appears from the plot to be a typo. However, please re-measure the 20dB bandwidth with the hopping function stopped.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.