


Appendix II

Internal Photographs




Internal View of EUT-2




Page 2 of 9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.




Internal View of EUT-4




Page 3 of 9




Internal View of EUT-6



Page 4 of 9




Internal View of EUT-8




Page 5 of 9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


Internal View of EUT-9




Internal View of EUT-10




Page 6 of 9




Internal View of EUT-12




Page 7 of 9




Internal View of EUT-14



Page 8 of 9



Internal View of EUT-16



Page 9 of 9