











MADE IN CHINA IC:30218-IT109S18

HVIN:ME-IT109-L-V1.1 ME-IT109-R-V1.1



Please clean both charging contacts of the earbud and charger seat, and remove sweat perspiration and dirt dot to avoid charging failed