Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)




Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

