

page 1 of 5

ANNEX B EXTERNAL PHOTOS




136117_DFS3.JPG: ODIN-W160 (cB-driver), soldered on cB-0957, top view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298



ANNEX B EXTERNAL PHOTOS




136117_DFS4.JPG: ODIN-W160 (cB-driver), soldered on cB-0957, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298
 page 2 of 5



ANNEX B **EXTERNAL PHOTOS**



136117_DFS7.JPG: cB-0962 WGP development board, top view

Test Report No.: F145298E9 Order No.: 14-115298

Examiner: Manuel BASTERT Date of issue: 19 June 2015

page 3 of 5



page 4 of 5

ANNEX B EXTERNAL PHOTOS



136117_DFS8.JPG: cB-0962 WGP development board, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298



page 5 of 5

ANNEX B EXTERNAL PHOTOS



136117_DFS9.JPG: Type plate Cisco Access Point

Test Report No.: F145298E9 Order No.: 14-115298

Examiner: Manuel BASTERT Date of issue: 19 June 2015