

October 24, 2001

According to Telular Corporation, there is not a tuneup procedure necessary for this device.