
Appendix C. Set up Photograph Conducted Emission (Cradle+USB)



FRONT VIEW




REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C9 Issued Date : Nov. 15, 2004

Report No.: FR451503-01





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C9
Issued Date : Nov. 15, 2004



Conducted Emission (Cradle)



FRONT VIEW



Page No.


: C3 of C9


Issued Date : Nov. 15, 2004

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C9
Issued Date : Nov. 15, 2004



Conducted Emission (EUT)




FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C9 Issued Date : Nov. 15, 2004





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C6 of C9
Issued Date : Nov. 15, 2004



Conducted Emission (USB)




FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C7 of C9 Issued Date : Nov. 15, 2004







TEL: 886-2-2696-2468 FAX: 886-2-2696-2255



Radiation Emission



FRONT VIEW



REAR VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C9 of C9 Issued Date : Nov. 15, 2004