

Sep 12, 2002

RE: Universal Scientific Industrial Co., Ltd.
FCC ID: IXMCF114100

Dear Timothy:

After the review of your comments, we have made some modifications upon your advice; they are summarized as follows:

1. The Block Diagram updated with adding all the frequency of the oscillators shown, is uploaded.
2. The manufacturer wants the product being locked in its working configuration at the "HANDHELD" mode. Please refer to the declaration of locking the configuration by the manufacturer attached.
3. Thanks for your kindly reminding about the report. The negative sign is inserted and please find the modified one uploaded.
4. The Compliance Information is inserted to the manual. Please find the modified one uploaded.

Should you have any questions or more information is needed, please don't hesitate to ask us.
Thank you.

Sincerely yours,
Eric Wong
Project Engineer
Training Research Co Ltd.