

11AX20MIMO_Ant3_5200



11AX20MIMO_Ant4_5200



11AX20MIMO_Ant1_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_5240



11AX20MIMO_Ant3_5240



11AX20MIMO_Ant4_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5745



11AX20MIMO_Ant2_5745



11AX20MIMO_Ant3_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant4_5745



11AX20MIMO_Ant1_5785



11AX20MIMO_Ant2_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant3_5785



11AX20MIMO_Ant4_5785



11AX20MIMO_Ant1_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_5825



11AX20MIMO_Ant3_5825



11AX20MIMO_Ant4_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5190



11AX40MIMO_Ant2_5190

11AX40MIMO_Ant3_5190

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_5190



11AX40MIMO_Ant1_5230



11AX40MIMO_Ant2_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant3_5230



11AX40MIMO_Ant4_5230



11AX40MIMO_Ant1_5755

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_5755



11AX40MIMO_Ant3_5755



11AX40MIMO_Ant4_5755

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5795



11AX40MIMO_Ant2_5795



11AX40MIMO_Ant3_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_5795



11AX80MIMO_Ant1_5210



11AX80MIMO_Ant2_5210

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant3_5210



11AX80MIMO_Ant4_5210



11AX80MIMO_Ant1_5775

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_5775



11AX80MIMO_Ant3_5775



11AX80MIMO_Ant4_5775

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11.6. APPENDIX F: DUTY CYCLE

11.6.1. Test Result

Test Mode	On Time (msec)	Period (msec)	Duty Cycle x (Linear)	Duty Cycle (%)	Duty Cycle Correction Factor (dB)	1/T Minimum VBW (kHz)	Final setting For VBW (kHz)
11A	1.39	1.45	0.9586	95.86	0.18	0.72	1
11AX20MIMO	0.35	0.40	0.8750	87.50	0.58	2.86	3
11AX40MIMO	0.22	0.28	0.7857	78.57	1.05	4.55	5
11AX80MIMO	0.34	0.39	0.8718	87.18	0.60	2.94	3
11AX160MIMO	0.33	0.39	0.8462	84.62	0.73	3.03	4

Note:
Duty Cycle Correction Factor=10log (1/x).
Where: x is Duty Cycle (Linear)
Where: T is On Time
If that calculated VBW is not available on the analyzer then the next higher value should be used.

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11.6.2. Test Graphs

11A_Ant1_5180

11AX20MIMO_Ant1_5180

11AX40MIMO_Ant1_5190

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_5210

11AX160MIMO_Ant1_5250

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11.7. APPENDIX G: FREQUENCY STABILITY

11.7.1. Test Result

Frequency Error vs. Voltage									
802.11a 20: 5200MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
T_N	V_L	5199.9775	-4.33	5200.0193	3.72	5199.9832	-3.23	5200.0029	0.55
T_N	V_N	5200.0131	2.53	5199.9796	-3.92	5200.0225	4.32	5200.0216	4.15
T_N	V_H	5199.9979	-0.41	5199.9955	-0.86	5200.0013	0.25	5200.0223	4.29

Frequency Error vs. Temperature									
802.11a 20: 5200MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
40	V_N	5199.9884	-2.23	5199.9860	-2.69	5199.9778	-4.26	5199.9823	-3.41
30	V_N	5200.0009	0.17	5200.0132	2.54	5199.9894	-2.03	5200.0035	0.68
20	V_N	5200.0110	2.11	5200.0219	4.20	5200.0225	4.34	5200.0141	2.71
10	V_N	5200.0246	4.74	5199.9990	-0.20	5200.0070	1.35	5199.9857	-2.75
0	V_N	5200.0114	2.19	5199.9898	-1.97	5200.0040	0.77	5200.0174	3.35

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Frequency Error vs. Voltage									
802.11a 20: 5825 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
T_N	V_L	5825.0055	0.94	5825.0243	4.17	5825.0226	3.89	5825.0093	1.60
T_N	V_N	5824.9817	-3.14	5825.0126	2.17	5825.0107	1.84	5824.9794	-3.54
T_N	V_H	5825.0186	3.19	5825.0217	3.72	5825.0058	0.99	5825.0187	3.20
Frequency Error vs. Temperature									
802.11a 20: 5825 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
40	V_N	5824.9963	-0.64	5825.0107	1.83	5824.9971	-0.50	5824.9928	-1.24
30	V_N	5825.0017	0.29	5825.0222	3.82	5824.9851	-2.56	5824.9940	-1.03
20	V_N	5825.0166	2.85	5824.9760	-4.12	5825.0091	1.57	5824.9954	-0.79
10	V_N	5824.9773	-3.89	5825.0140	2.41	5824.9862	-2.36	5825.0127	2.18
0	V_N	5824.9854	-2.50	5825.0217	3.72	5824.9839	-2.76	5825.0055	0.95

Note:
1. All antennas and test modes have been tested, only the worst data record in the report.
2. For the detail Test Conditions, please refer to section 7.5.

END OF REPORT

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.