SONY

Sony Mobile Communications, Inc.
4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

Date: June 28, 2017

Internal Photos

FCC ID: PY7-46331W

Without external cosmetic parts

(Top Side)

(Front Side)

(Rear Side)

(Right Side)

(Left Side)

(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without internal plate

(Top Side)

(Front Side)

(Rear Side)

(Right Side)

(Left Side)

(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without Panel and Battery

(Top Side)

(Front Side)

(Rear Side)

(Right Side)

(Left Side)

(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without PBA

(Top Side/Bottom Side Photo is same as p.10)

(Front Side)

(Rear Side)



(Right Side)

(Left Side)



Antenna location

*Zoom up photo from above Rear Side and Left Side photo.

(Rear Side)



(Left Side)



It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without Head and Base block

(Top Side)



(Front Side)



(Rear Side)



(Right Side)



(Left Side)



(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Base block

(Top Side)



(Front Side)



(Rear Side)



(Right Side)



(Left Side)

(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Base block without external parts

(Top Side)



(Front Side)



(Rear Side)



(Right Side)

(Left Side)



(SW PBA block)

(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Head block

(Top Side)

(Front Side)

(Rear Side)

(Right Side)

(Left Side)

(Internal PCB)



(Bottom Side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

PBA Photo

(AL PBA A-side)



(AL PBA B-side)



(Batt PBA A-side)

(Batt PBA B-side)



(BS PBA A-side)



(BS PBA B-side)



It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.
4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

(ELED PBA A-side)



(ELED PBA B-side)



(HD PBA A-side)



(HD PBA B-side)



(KS PBA A-side)

(KS PBA B-side)

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.
4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

(LED PBA A-side)



(LED PBA B-side)



(Motor PBA A-side)



(Motor PBA B-side)

(Main PBA A-side)



(Main PBA B-side)



It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

SONY

Sony Mobile Communications, Inc.
4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

(Main PBA A-side without plate)



(Main PBA B-side without plate)

(SCU PBA A-side)



(SCU PBA B-side)

(SW PBA A-side)



(SW PBA B-side)



It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.

Sony Mobile Communications, Inc.
4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

Panel



Battery

It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.