APPENDIX B. Photographs of EUT









There are no end user or field technician serviceable parts inside this cabinet.

This equipment should be installed in accordance with ANSI/NFPA 72, (National Fire Protection Association, Batterymarch Park, Quincy, MA 02269).
Printed information describing proper installation, operation, testing, maintenance, evacuation planning, and repair service is to be provided with this equipment.

Warning
Owner's instruction notice:
'Not to be removed by anyone except occupant, System is intended to be checked by a qualified technician at least every 3 years.

WARNING
THIS UNIT INCLUDES AN ALARM VERIFICATION FEATURE THAT WILL RESULT IN A DELAY OF THE SYSTEM ALARM SIGNAL FROM THE INDICATED CIRCUITS.
THE TOTAL DELAY(CONTROL UNIT PLUS SMOKE DETECTORS) SHALL NOT EXCEED 60 SECONDS.
NO OTHER SMOKE DETECTOR SHALL BE CONNECTED TO THESE CIRCUITS UNLESS APPROVED BY THE LOCAL AUTHORITY HAVING JURISDICTION.

CIRCUIT (ZONE)	CONTROL UNIT DELAY-SEC.		SMOKE DETECTOR	
			MODEL	DELAY-SEC.
			SW-ATT-SMK	

technicolor
FCC ID: D6ADLC200C
Residential Fire and Burglar Control Unit
Model: DLC-200C US P/N: DL-432331524T-K9
ALSO CLASSIFIED IN ACCORDANCE WITH ANSI/SIA CP-01-2010
SECURITY SIGNALING
LISTED
Fire Alarm and Security Equipment
H/W Rev: 1.0.3
Factory ID: F28
SKU: 6712A
Date of MFG: 01/2016
IMEI: 357355070060006
ANSI/NFPA 72
Test system once per week
Installation Drawing
Document Number
ATT-UM-V1-201212 for Details
Warning
Owner's instruction notice
'Not to be removed by
anyone except occupant'
Made in China

technicolor
FCC ID: D6XDLC200C
Residential Fire and Burglar Control Unit
Model: DLC-200C US P/N: DL-43233152AT-K9
ALSO CLASSIFIED IN ACCORDANCE WITH ANSI/SIA CP-01-2010
SECURITY SIGNALING
UL
LISTED
4XX0
Fire Alarm and Security Equipment
H/W Rev: 1.0.3
Factory ID: F28
SKU: 6712A
Date of MFG:
01/2016
IMEI: 357355070060006
ANSI/NFPA 72
Test system once per week
Installation Drawing
Document Number
ATT-UM-V1-201212 for Details
Warning
Owner's instruction notice:
'Not to be removed by
anyone except occupant'
Made in China


WAN
LAN


WAN
LAN

technicolor
Residential Fire and Burglar Control Unit
Model: DLC-200C US P/N: DL-43233152AT-K9
ALSO CLASSIFIED IN ACCORDANCE WITH ANSI/SIA CP-01-2010
S/N: 123638930
WAN MAC: CC0DEC357DD2
Wi-Fi MAC: CC0DEC357DD4
SECURITY SIGNALING
LISTED
AXXB
Fire Alarm and Security Equipment
FCC ID: D6XDLC200
Input Power: PoE+ 25.5W
H/W Rev: 1.0.3
DLC F/W: 1.02.72
DLA F/W: 1.0.27 build 39621
Factory ID: F28
Date of MFG: 01/2016
Made in China


ANSI/NFPA 72
Test system once per week
Installation Drawing
Document Number ATT-UM-V1-201212 for Details
Warning
Owner's instruction notice:
'Not to be removed by anyone except occupant'

Docum
Warr
Owner'
'Not to