

11AX40MIMO_Ant13_7005



11AX40MIMO_Ant5_7085



11AX40MIMO_Ant7_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_7085



11AX40MIMO_Ant13_7085



11AX80MIMO_Ant5_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6145



11AX80MIMO_Ant11_6145



11AX80MIMO_Ant13_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6225



11AX80MIMO_Ant7_6225



11AX80MIMO_Ant11_6225

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant13_6225



11AX80MIMO_Ant5_6385



11AX80MIMO_Ant7_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant11_6385



11AX80MIMO_Ant13_6385



11AX80MIMO_Ant5_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6465



11AX80MIMO_Ant11_6465



11AX80MIMO_Ant13_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6545



11AX80MIMO_Ant7_6545



11AX80MIMO_Ant11_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant13_6545



11AX80MIMO_Ant5_6705



11AX80MIMO_Ant7_6705

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant11_6705



11AX80MIMO_Ant13_6705



11AX80MIMO_Ant5_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6865



11AX80MIMO_Ant11_6865



11AX80MIMO_Ant13_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6945



11AX80MIMO_Ant7_6945



11AX80MIMO_Ant11_6945

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant13_6945



11AX80MIMO_Ant5_7025



11AX80MIMO_Ant7_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant11_7025



11AX80MIMO_Ant13_7025



11AX160MIMO_Ant5_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6185



11AX160MIMO_Ant11_6185



11AX160MIMO_Ant13_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6345



11AX160MIMO_Ant7_6345



11AX160MIMO_Ant11_6345

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant13_6345



11AX160MIMO_Ant5_6505



11AX160MIMO_Ant7_6505

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant11_6505



11AX160MIMO_Ant13_6505



11AX160MIMO_Ant5_6665

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6665



11AX160MIMO_Ant11_6665



11AX160MIMO_Ant13_6665

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6825



11AX160MIMO_Ant7_6825



11AX160MIMO_Ant11_6825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.