

11AX20MIMO_Ant13_6535



11AX20MIMO_Ant5_6715



11AX20MIMO_Ant7_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant11_6715



11AX20MIMO_Ant13_6715



11AX20MIMO_Ant5_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_6875



11AX20MIMO_Ant11_6875



11AX20MIMO_Ant13_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6895



11AX20MIMO_Ant7_6895



11AX20MIMO_Ant11_6895

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant13_6895



11AX20MIMO_Ant5_7015



11AX20MIMO_Ant7_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant11_7015



11AX20MIMO_Ant13_7015



11AX20MIMO_Ant5_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_7095



11AX20MIMO_Ant11_7095



11AX20MIMO_Ant13_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6125



11AX40MIMO_Ant7_6125



11AX40MIMO_Ant11_6125

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6125



11AX40MIMO_Ant5_6285



11AX40MIMO_Ant7_6285

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6285



11AX40MIMO_Ant13_6285



11AX40MIMO_Ant5_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6405



11AX40MIMO_Ant11_6405



11AX40MIMO_Ant13_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6445



11AX40MIMO_Ant7_6445



11AX40MIMO_Ant11_6445

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6445



11AX40MIMO_Ant5_6485



11AX40MIMO_Ant7_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6485



11AX40MIMO_Ant13_6485



11AX40MIMO_Ant5_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6525



11AX40MIMO_Ant11_6525



11AX40MIMO_Ant13_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6725



11AX40MIMO_Ant7_6725



11AX40MIMO_Ant11_6725

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6725



11AX40MIMO_Ant5_6845



11AX40MIMO_Ant7_6845

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6845



11AX40MIMO_Ant13_6845



11AX40MIMO_Ant5_6885

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6885



11AX40MIMO_Ant11_6885



11AX40MIMO_Ant13_6885

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_7005



11AX40MIMO_Ant7_7005



11AX40MIMO_Ant11_7005

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.