

11AX80MIMO_Ant0_6465



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant0_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6545



11AX80MIMO_Ant0_6705



11AX80MIMO_Ant1_6705

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_6785



11AX80MIMO_Ant1_6785



11AX80MIMO_Ant0_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6865



11AX80MIMO_Ant0_6945



11AX80MIMO_Ant1_6945

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_7025



11AX80MIMO_Ant1_7025



11AX160MIMO_Ant0_6025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6025



11AX160MIMO_Ant0_6185



11AX160MIMO_Ant1_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant0_6345



11AX160MIMO_Ant1_6345



11AX160MIMO_Ant0_6505

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6505



11AX160MIMO_Ant0_6665



11AX160MIMO_Ant1_6665

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant0_6825



11AX160MIMO_Ant1_6825



11AX160MIMO_Ant0_6985

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6985



11BE20MIMO_Ant0_5955



11BE20MIMO_Ant1_5955

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant0_6175



11BE20MIMO_Ant1_6175



11BE20MIMO_Ant0_6415

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_6415



11BE20MIMO_Ant0_6435



11BE20MIMO_Ant1_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant0_6475



11BE20MIMO_Ant1_6475



11BE20MIMO_Ant0_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_6515



11BE20MIMO_Ant0_6535



11BE20MIMO_Ant1_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant0_6715



11BE20MIMO_Ant1_6715



11BE20MIMO_Ant0_6855

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_6855



11BE20MIMO_Ant0_6875



11BE20MIMO_Ant1_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant0_7015



11BE20MIMO_Ant1_7015



11BE20MIMO_Ant0_7115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_7115



11BE40MIMO_Ant0_5965



11BE40MIMO_Ant1_5965

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant0_6165



11BE40MIMO_Ant1_6165



11BE40MIMO_Ant0_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_6405



11BE40MIMO_Ant0_6445



11BE40MIMO_Ant1_6445

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant0_6485



11BE40MIMO_Ant1_6485



11BE40MIMO_Ant0_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_6525



11BE40MIMO_Ant0_6565



11BE40MIMO_Ant1_6565

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant0_6725



11BE40MIMO_Ant1_6725



11BE40MIMO_Ant0_6845

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.