10. SETUP PHOTOS

RADIATED EMISSION BELOW 30 MHz

RADIATED EMISSIONS BELOW 30MHz (Front - Standby)



RADIATED EMISSIONS BELOW 30MHz (Back- Standby)



UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701I
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS BELOW 30MHz (Front – With iPhone)



RADIATED EMISSIONS BELOW 30MHz (Back - With iPhone)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS BELOW 30MHz (Front – With iPhone 3mm Gap)



RADIATED EMISSIONS BELOW 30MHz (Back - With iPhone 3mm Gap)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

RADIATED EMISSIONS BELOW 30MHz (Front – With Receiver 10W Load)



RADIATED EMISSIONS BELOW 30MHz (Back - With Receiver 10W load)



UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701I
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

RADIATED EMISSIONS BELOW 30MHz (Front – With Receiver 10W load 3mm Airgap)



RADIATED EMISSIONS BELOW 30MHz (Back - With Receiver 10W Load 3mm Airgap)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

RADIATED EMISSION ABOVE 30 MHz

RADIATED EMISSIONS ABOVE 30 MHz (FRONT - STANDBY)



RADIATED EMISSIONS ABOVE 30 MHz (BACK - STANDBY)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS ABOVE 30 MHz (Front – With iPhone)



RADIATED EMISSIONS ABOVE 30 MHz (Back – With iPhone)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS ABOVE 30 MHz (Front – With Phone 3mm Gap)



RADIATED EMISSIONS ABOVE 30 MHz (Back – With Phone 3mm gap)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS ABOVE 30 MHz (Front – With Receiver 10W Load)



RADIATED EMISSIONS ABOVE 30 MHz (Back – With Receiver 10W Load)

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

OPERATING

RADIATED EMISSIONS ABOVE 30 MHz (Front – With Receiver 10W Load 3mm Airgap)



RADIATED EMISSIONS ABOVE 30 MHz (Back – With Receiver 10W Load 3mm Airgap)



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

AC LINE CONDUCTED EMISSIONS MEASUREMENT SETUP (STANDBY MODE)

Front

Back

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

AC LINE CONDUCTED EMISSIONS MEASUREMENT SETUP (CHARGING MODE

Front- With iPhone



Back – With iPhone

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701I
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Front- With Phone 3mm Gap

Back – With Phone 3mm gap



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Front- With Receiver 10W Load

Back – With Receiver 10W Load

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701I
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Front- With Receiver 10W Load 3mm Airgap



Back – With Receiver 10W Load 3mm Airgap



END OF REPORT

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4701I
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.