

11AX40MIMO_Ant3_5270



11AX40MIMO_Ant1_5310



11AX40MIMO_Ant3_5310

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5510



11AX40MIMO_Ant3_5510



11AX40MIMO_Ant1_5550

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant3_5550



11AX40MIMO_Ant1_5670



11AX40MIMO_Ant3_5670

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5710



11AX40MIMO_Ant3_5710



11AX40MIMO_Ant1_5755

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant3_5755



11AX40MIMO_Ant1_5795



11AX40MIMO_Ant3_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_5210



11AX80MIMO_Ant3_5210



11AX80MIMO_Ant1_5290

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant3_5290



11AX80MIMO_Ant1_5530



11AX80MIMO_Ant3_5530

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_5610



11AX80MIMO_Ant3_5610



11AX80MIMO_Ant1_5690

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant3_5690



11AX80MIMO_Ant1_5775



11AX80MIMO_Ant3_5775

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_5250



11AX160MIMO_Ant3_5250



11AX160MIMO_Ant1_5570

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant3_5570



11BE20MIMO_Ant1_5180



11BE20MIMO_Ant3_5180

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5200



11BE20MIMO_Ant3_5200



11BE20MIMO_Ant1_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5240



11BE20MIMO_Ant1_5260



11BE20MIMO_Ant3_5260

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5280



11BE20MIMO_Ant3_5280



11BE20MIMO_Ant1_5320

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5320



11BE20MIMO_Ant1_5500



11BE20MIMO_Ant3_5500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5580



11BE20MIMO_Ant3_5580



11BE20MIMO_Ant1_5700

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5700



11BE20MIMO_Ant1_5720



11BE20MIMO_Ant3_5720

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5745



11BE20MIMO_Ant3_5745



11BE20MIMO_Ant1_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5785



11BE20MIMO_Ant1_5825



11BE20MIMO_Ant3_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_5190



11BE40MIMO_Ant3_5190



11BE40MIMO_Ant1_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.