认证标志，不同认证机构的不一样
需要按实际认证标志替换

The certification mark is different for different certification bodies
and needs to be replaced according to the actual certification mark

日期号：MM.YYYY
Date number
规则：英文月份全称+年份4位
Rules: Full name of English month + year 4 digits

TOSHIBA

Model/Modelo:EC9P04-S00K00
Household Microwave Oven
(Not for commercial use)
Input 120VAC 60Hz,
Microwave Input 1450 W
Output 900 W, 2450 MHz
RATED INPUT(Grill): 1000 W
RATED INPUT(Conviction): 1500 W
Manufacture Date / Date de fabrication:
MM.YYYY
FCC ID:VG8XC9P04YYKE

c UL us
LISTED
54NJ
E214180

Four à micro-ondes familial
(non destine a l'usage commercial)
Alinentation 120VAC 60Hz, monophase 1450 W
Puissance 900 W, 2450 MHz
Entrée grillée: 1000 W, Entrée notée (Conviction): 1500 W
Made in China / Fabricado en China
Guangdong Midea Kitchen Appliances
Manufacturing Co.,Ltd.
No.6, Yong An Road,Beijiao, Shunde, Foshan,
Guangdong,P.R.China
THIS DEVICE COMPLIES WITH DHHS RADIATION
PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J.

NOT FOR BUILT-IN INSTALLATION.

WARNING: SHOCK HAZARD. CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.

WARNING: CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRICAL SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL: DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR AND LOW VOLTAGE TRANSFORMER.

WARNING: SHOCK HAZARD. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF HIGH INTERNAL VOLTAGES. DO NOT REMOVE FASTENERS.

A SHORT POWER-SUPPLY CORD IS PROVIDED TO REDUCE THE RISKS RESULTING FROM BECOMING ENTANGLED IN OR TRIPPING OVER A LONGER CORD.

-LONGER CORD SETS OR EXTENSION CORDS ARE AVAILABLE AND MAY BE USED IF CARE IS EXERCISED IN THEIR USE.

-IF A LONG CORD OR EXTENSION CORD IS USED:

A) THE MARKED ELECTRICAL RATING OF THE CORD SET OR EXTENSION CORD SHOULD BE AT LEAST AS GREAT AS THE ELECTRICAL RATING OF THE APPLIANCE.
B) THE EXTENSION CORD MUST BE A GROUNDING-TYPE- 3-WIRE CORD; AND
C) THE LONGER CORD SHOULD BE ARRANGED SO THAT IT WILL NOT DRAPE OVER THE COUNTER TOP OR TABLETOP WHERE IT CAN BE PULLED ON BY CHILDREN OR TRIPPED OVER UNINTENTIONALLY.

THIS ISM APPARATUS MEETS ALL REQUIREMENTS OF THE CANADIAN INTERFERENCE CAUSING EQUIPMENT REGULATIONS.

CAUTION: THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING: DISCONNECT ELECTRIC POWER BEFORE SERVICING

CAN ICES-1.

CAUTION MICROWAVES
MISE EN GARDE MICRO-ONDES

c UL

Energy Verified
Rendement
Énergétique Vérifié

CET APPAREIL NE CONVIENT PAS AUX INSTALLATIONS ENCASTRÉES.

AVERTISSEMENT : RISQUE D'ÉLECTROCUTION. BRANCHEZ SEULEMENT À DES PRISES DE COURANT ADÉQUATEMENT MISES À LA TERRE.

AVERTISSEMENT : CERTAINES PIÈCES INTERNES NE SONT PAS MISES À LA TERRE INTENTIONNELLEMENT ET PEUVENT CONSTITUER UN RISQUE D'ÉLECTROCUTION SEULEMENT DURANT L'ENTRETIEN. PERSONNEL DE SERVICE : NE PAS FAIRE CONTACT AUX PIÈCES SUIVANTES LORSQUE L'APPAREIL EST SOUS TENSION : MOTEUR DU VENTILATEUR ET TRANSFORMATEUR DE BASSE TENSION.

AVERTISSEMENT : RISQUE D'ÉLECTROCUTION. DE LA BOULONNERIE NON AMOVIBLE EST FOURNIE À CAUSE DE LA HAUTE TENSION À L'INTÉRNE. NE PAS ENLEVER LA BOULONNERIE.

UN COURT CORDON D'ALIMENTATION EST FOURNI AFIN DE RÉDUIRE LES RISQUES D'EMMÊLEMENT ET DE TRÉBUCHEMENT ASSOCIÉS À UN CORDON PLUS LONG.

-DES CORDONS PLUS LONGS OU RALLONGES SONT DISPONIBLES ET PEUVENT ÊTRE UTILISÉS SI DES PRÉCAUTIONS SONT PRISES LORS DE LEUR.

-SI UN CORDON LONG OU UNE RALLONGE EST UTILISÉE :

A) LES CARACTÉRISTIQUES ÉLECTRIQUES INDIQUÉES SUR LE CORDON OU SUR LA RALLONGE DEVRAIENT ÊTRE AU MOINS AUSSI ÉLEVÉS QUE LES CARACTÉRISTIQUES ÉLETRIQUES DE L'APPAREIL.
B) LA RALLONGE DOIT ÊTRE DE TYPE CORDON 3 FILS MIS À LA TERRE ; ET
C) LE CORDON LE PLUS LONG DEVRAIT ÊTRE ARRANGÉ DE FAÇON À NE PAS COUVRIR LE HAUT DE COMPTOIR OU LE DESSUS DE LA TABLE OÙ IL PEUT ÊTRE TIRÉ PAR DES ENFANTS OU FAIRE TRÉBUCHER INVOLONTAIREMENT.

CET APPAREIL I.S.M. SE CONFORME À TOUTES LES EXIGENCES DES RÈGLEMENTS CANADIENS CONCERNANT L'ÉQUIPEMENT CAUSANT DES INTERFÉRENCES.

MISE EN GARDE : CET APPAREIL DOIT ÊTRE RÉPARÉ SEULEMENT PAR DU PERSONNEL D'ENTRETIEN ADÉQUATEMENT QUALIFIÉ. CONSULTEZ LE MANUEL D'ENTRETIEN POUR CONNAÎTRE LES PROCÉDURES D'ENTRETIEN ADÉQUATES AFIN D'ASSURER LA CONTINUATION DE LA CONFORMITÉ AUX NORMES FÉDÉRALES DE PERFORMANCE DES FOURS À MICRO-ONDES ET POUR LES PRÉCAUTIONS À PRENDRE AFIN D'ÉVITER UNE EXPOSITION POSSIBLE À L'ÉNERGIE MICRO-ONDES EXCESSIVE.

AVERTISSEMENT : DÉCONNECTER DU CIRCUIT D' ALIMENTATION ÉLECTRIQUE AVANT L' ENTRETIEN

NMB-1.

Label Location Information