

11A_Ant0_5260



11A_Ant0_5280



11A_Ant0_5320

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_5500



11A_Ant0_5580



11A_Ant0_5700

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_5720



11A_Ant0_5745



11A_Ant0_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_5825



11N20MIMO_Ant0_5180



11N20MIMO_Ant0_5200

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5240



11N20MIMO_Ant0_5260



11N20MIMO_Ant0_5280

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5320



11N20MIMO_Ant0_5500



11N20MIMO_Ant0_5580

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5700



11N20MIMO_Ant0_5720



11N20MIMO_Ant0_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20MIMO_Ant0_5785



11N20MIMO_Ant0_5825



11N40MIMO_Ant0_5190

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5230



11N40MIMO_Ant0_5270



11N40MIMO_Ant0_5310

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5510



11N40MIMO_Ant0_5550



11N40MIMO_Ant0_5670

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N40MIMO_Ant0_5710



11N40MIMO_Ant0_5755



11N40MIMO_Ant0_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant0_5210



11AC80MIMO_Ant0_5290



11AC80MIMO_Ant0_5530

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant0_5610



11AC80MIMO_Ant0_5690



11AC80MIMO_Ant0_5775

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5180



11AX20MIMO_Ant0_5200



11AX20MIMO_Ant0_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5260



11AX20MIMO_Ant0_5280



11AX20MIMO_Ant0_5320

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5500



11AX20MIMO_Ant0_5580



11AX20MIMO_Ant0_5700

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5720



11AX20MIMO_Ant0_5745



11AX20MIMO_Ant0_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5825



11AX40MIMO_Ant0_5190



11AX40MIMO_Ant0_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5270



11AX40MIMO_Ant0_5310



11AX40MIMO_Ant0_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.