
57.00 mm
32.00 mm
PHILIPS
Model No.:FX10/37
AC 100-240V~50/60Hz,60W
5V 500mA
FCC ID:2AR2SFX1037
IC:24589-FX1037
HVIN:FX10
This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.
CAN ICES-003(B)/NMB-003(B)
Complies with 21 CFR 1040.10 and 1040.11 except for conformance with IEC 60825-1 Ed. 3., as described in Laser Notice No. 56, dated May 8, 2019
Model No.: FX10/37
Serial No.: XXXXXXXXXXXXXXXXXX
LISTED
AUDIO EQUIPMENT
E506295
Made in China
TPV USA Corp.
6525 Morrison Blvd #200 Charlotte, NC – 28211, USA

张粘示意图：


TR
WR
TL
WL
R R L L
HIGH LOW HIGH LOW
6Ω 6Ω
L
R
AUX IN
FM
ANTENNA
100-240V ~50/60Hz
AC MAINS ~
CLASS 1
LASER PRODUCT
PHILIPS
Model No.:FX10/37
AC 100-240V~50/60Hz,60W
5V 500mA
FCC ID:2AR2SFX1037
IC:24589-FX1037
HVIN:FX10
This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.
CAN ICES-003(B)/NMB-003(B)
Complies with 21 CFR 1040.10 and 1040.11 except for conformance with IEC 60825-1 Ed. 3., as described in Laser Notice No. 56, dated May 8, 2019
Model No.: FX10/37
Serial No.: XXXXXXXXXXXXXXXXXX
LISTED
AUDIO EQUIPMENT
E506295
Made in China
TPV USA Corp.
6525 Morrison Blvd #200 Charlotte, NC – 28211, USA
CAUTION
RISK OF ELECTRIC SHOCK DO NOT OPEN
ATTENTION: RISQUE DE CHOC ÉLECTRIQUE - NE PAS OUVRIR
ADVERTÊNCIA - PRECAUCION
NÃO ABRIR, RISCO DE CHOQUE ELÉTRICO.
NO ABRIR, RIESGO DE CHOQUE ELECTRICO.
ATENÇAO - ATENCION
VERIFIQUE SE A VOLTAGEM DE ALIMENTAÇÃO ESTÁ CORRETA PARA SEU APARELHO.
VERIFIQUE QUE EL VOLTAJE DE ALIMENTACION SEA EL REQUERIDO PARA SU APARATO.
PARA EVITAR RISCO DE CHOQUE ELÉTRICO, NÃO ABRA A TAMPA.
CASO PRECISE DE QUALQUER SERVIÇO, PROCURE A REDE AUTORIZADA PHILIPS.
PARA EVITAR EL RIESGO DE CHOQUE ELECTRICO, NO QUITE LA TAPA.
EN CASO DE REQUERIR SERVICIO, DIRIJASE AL PERSONAL AUTORIZADO DE PHILIPS.
GARANTIA INCLÚIDA NO MANUAL DE INSTRUÇÕES
GARANTIA INCLUIDA EN EL INSTRUCTIVO DEL USO