

11A_Ant3_5260



11A_Ant3_5280



11A_Ant3_5320



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11A_Ant3_5500



11A_Ant3_5580



11A_Ant3_5700



11A_Ant3_5720

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant3_5745



11A_Ant3_5785



11A_Ant3_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX20SISO_Ant3_5180



11AX20SISO_Ant3_5200



11AX20SISO_Ant3_5240



11AX20SISO_Ant3_5260

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20SISO_Ant3_5280



11AX20SISO_Ant3_5320



11AX20SISO_Ant3_5500



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX20SISO_Ant3_5580



11AX20SISO_Ant3_5700



11AX20SISO_Ant3_5720



11AX20SISO_Ant3_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20SISO_Ant3_5785



11AX20SISO_Ant3_5825



11AX40SISO_Ant3_5190



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX40SISO_Ant3_5230



11AX40SISO_Ant3_5270



11AX40SISO_Ant3_5310



11AX40SISO_Ant3_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX40SISO_Ant3_5550



11AX40SISO_Ant3_5670



11AX40SISO_Ant3_5710



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX40SISO_Ant3_5755



11AX40SISO_Ant3_5795



11AX80SISO_Ant3_5210



11AX80SISO_Ant3_5290

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80SISO_Ant3_5530



11AX80SISO_Ant3_5610



11AX80SISO_Ant3_5690

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80SISO_Ant3_5775



11AX160SISO_Ant3_5250



11AX160SISO_Ant3_5570



11N20SISO_Ant3_5180

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20SISO_Ant3_5200

11N20SISO_Ant3_5240



11N20SISO_Ant3_5260

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11N20SISO_Ant3_5280



11N20SISO_Ant3_5320



11N20SISO_Ant3_5500



11N20SISO_Ant3_5580

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11N20SISO_Ant3_5700



11N20SISO_Ant3_5720



11N20SISO_Ant3_5745



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11N20SISO_Ant3_5785



11N20SISO_Ant3_5825



11N40SISO_Ant3_5190



11N40SISO_Ant3_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.