

11BE40MIMO_Ant4_6405



11BE40MIMO_Ant9_6405



11BE40MIMO_Ant10_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6445



11BE40MIMO_Ant4_6445



11BE40MIMO_Ant9_6445

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant10_6445



11BE40MIMO_Ant3_6485



11BE40MIMO_Ant4_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant9_6485



11BE40MIMO_Ant10_6485



11BE40MIMO_Ant3_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6525



11BE40MIMO_Ant9_6525



11BE40MIMO_Ant10_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6565



11BE40MIMO_Ant4_6565



11BE40MIMO_Ant9_6565

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant10_6565



11BE40MIMO_Ant3_6725



11BE40MIMO_Ant4_6725

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant9_6725



11BE40MIMO_Ant10_6725



11BE40MIMO_Ant3_6845

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6845



11BE40MIMO_Ant9_6845



11BE40MIMO_Ant10_6845

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6885



11BE40MIMO_Ant4_6885



11BE40MIMO_Ant9_6885

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant10_6885



11BE40MIMO_Ant3_7005



11BE40MIMO_Ant4_7005

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant9_7005



11BE40MIMO_Ant10_7005



11BE40MIMO_Ant3_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_7085



11BE40MIMO_Ant9_7085



11BE40MIMO_Ant10_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_6145



11BE80MIMO_Ant4_6145



11BE80MIMO_Ant9_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant10_6145



11BE80MIMO_Ant3_6225



11BE80MIMO_Ant4_6225

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant9_6225



11BE80MIMO_Ant10_6225



11BE80MIMO_Ant3_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_6385



11BE80MIMO_Ant9_6385



11BE80MIMO_Ant10_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_6465



11BE80MIMO_Ant4_6465



11BE80MIMO_Ant9_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant10_6465



11BE80MIMO_Ant3_6545



11BE80MIMO_Ant4_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant9_6545



11BE80MIMO_Ant10_6545



11BE80MIMO_Ant3_6705

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.