

11A_Ant0_6455



11A_Ant0_6535



11A_Ant0_6695

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_6855



11A_Ant0_6935



11A_Ant0_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A_Ant0_7095



11AX20 _Ant0_5955



11AX20 _Ant0_6175

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20 _Ant0_6415



11AX20 _Ant0_6435



11AX20 _Ant0_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20 _Ant0_6515



11AX20 _Ant0_6535



11AX20 _Ant0_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20 _Ant0_6855



11AX20 _Ant0_6875



11AX20 _Ant0_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20 _Ant0_7115



11AX40 _Ant0_5965



11AX40 _Ant0_6165

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6405



11AX40 _Ant0_6445



11AX40 _Ant0_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6525



11AX40 _Ant0_6565



11AX40 _Ant0_6685

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_6845



11AX40 _Ant0_6885



11AX40 _Ant0_7005

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40 _Ant0_7085



11AX80 _Ant0_5985



11AX80 _Ant1_5985

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6145



11AX80 _Ant1_6145



11AX80 _Ant0_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant1_6385



11AX80 _Ant0_6465



11AX80 _Ant1_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6545



11AX80 _Ant1_6545



11AX80 _Ant0_6705

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant1_6705



11AX80 _Ant0_6785



11AX80 _Ant1_6785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant0_6865



11AX80 _Ant1_6865



11AX80 _Ant0_6945

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80 _Ant1_6945



11AX80 _Ant0_7025



11AX80 _Ant1_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant0_6025



11AX160 _Ant1_6025



11AX160 _Ant0_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant1_6185



11AX160 _Ant0_6345



11AX160 _Ant1_6345

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant0_6505



11AX160 _Ant1_6505



11AX160 _Ant0_6665

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant1_6665



11AX160 _Ant0_6825



11AX160 _Ant1_6825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160 _Ant0_6985



11AX160 _Ant1_6985



11BE20 _Ant0_5955

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.