Tx. Spurious NVNT g 2462MHz Ant6 Emission



Tx. Spurious NVNT n20 2412MHz Ant7 Ref



Tx. Spurious NVNT n20 2412MHz Ant7 Emission

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2412MHz Ant6 Ref



Tx. Spurious NVNT n20 2412MHz Ant6 Emission



Tx. Spurious NVNT n20 2437MHz Ant7 Ref

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2437MHz Ant7 Emission



Tx. Spurious NVNT n20 2437MHz Ant6 Ref



Tx. Spurious NVNT n20 2437MHz Ant6 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2462MHz Ant7 Ref



Tx. Spurious NVNT n20 2462MHz Ant7 Emission



Tx. Spurious NVNT n20 2462MHz Ant6 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2462MHz Ant6 Emission



Tx. Spurious NVNT n40 2422MHz Ant7 Ref



Tx. Spurious NVNT n40 2422MHz Ant7 Emission

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2422MHz Ant6 Ref



Tx. Spurious NVNT n40 2422MHz Ant6 Emission



Tx. Spurious NVNT n40 2437MHz Ant7 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2437MHz Ant7 Emission



Tx. Spurious NVNT n40 2437MHz Ant6 Ref



Tx. Spurious NVNT n40 2437MHz Ant6 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2452MHz Ant7 Ref



Tx. Spurious NVNT n40 2452MHz Ant7 Emission



Tx. Spurious NVNT n40 2452MHz Ant6 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2452MHz Ant6 Emission



Tx. Spurious NVNT ax20 2412MHz Ant7 Ref

Tx. Spurious NVNT ax20 2412MHz Ant7 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2412MHz Ant6 Ref



Tx. Spurious NVNT ax20 2412MHz Ant6 Emission



Tx. Spurious NVNT ax20 2437MHz Ant7 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2437MHz Ant7 Emission



Tx. Spurious NVNT ax20 2437MHz Ant6 Ref



Tx. Spurious NVNT ax20 2437MHz Ant6 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2462MHz Ant7 Ref



Tx. Spurious NVNT ax20 2462MHz Ant7 Emission



Tx. Spurious NVNT ax20 2462MHz Ant6 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2462MHz Ant6 Emission



Tx. Spurious NVNT ax40 2422MHz Ant7 Ref

Tx. Spurious NVNT ax40 2422MHz Ant7 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2422MHz Ant6 Ref



Tx. Spurious NVNT ax40 2422MHz Ant6 Emission



Tx. Spurious NVNT ax40 2437MHz Ant7 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2437MHz Ant7 Emission



Tx. Spurious NVNT ax40 2437MHz Ant6 Ref



Tx. Spurious NVNT ax40 2437MHz Ant6 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2452MHz Ant7 Ref



Tx. Spurious NVNT ax40 2452MHz Ant7 Emission



Tx. Spurious NVNT ax40 2452MHz Ant6 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2452MHz Ant6 Emission



END OF REPORT

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.