

NG!
SE DAMAGE
ONICS.
CONNECTING
RTS INSIDE
CAL SHOCK
INTERNAL
CONNECTING
ATTERY.

er operation of
controlled by
e alarm
permitted only
ving jurisdiction.
ected to a police
0021766 Rev A

US Fire Protection Regulatory Information
Install according to NFPA 72. (National Fire
Protection Association, Batterymarch Park, Quincy,
MA 02269). Printed information describing proper
installation, operation, testing, maintenance,
evacuation planning, and repair service is to be
provided with this equipment. Made in China


Battery and System Test.
To test the console, notify the Central
Station of the test, disconnect AC
power supply from the wall outlet and
press user instructions for details.

10021767 X1



To test the console, notify the Central Station of the test, disconnect AC power supply from the wall outlet and press user instructions for details.

10021767 X1






FIRMWARE v1.08



J3

S/N 1862020009972001




2GIG

© 2017

10018937

REV A

PA CP 5 94V-0
KT E243951
1834





6X ^ 3E9VWMM

IMEI: 01351800 - 3811342

2GIG - GC3GAX - A
SN: 1703120004274590

Telit HE910-NAR
SNR: 007130071974248
Model: HE910-NAR
FCC ID: R17HE910NA
IC: 5131A-HE910NA
Designed in Italy, Made in China

FIRMWARE v1.21

2GIG - GC25 - 345E
1828020008512135

SECURITY & CONTROL
10021254 X
PORTTEK
© 2019