

11BE20 _Ant1_5955



11BE20 _Ant0_6175



11BE20 _Ant1_6175

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6415



11BE20 _Ant1_6415



11BE20 _Ant0_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant1_6435



11BE20 _Ant0_6475



11BE20 _Ant1_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6515



11BE20 _Ant1_6515



11BE20 _Ant0_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant1_6535



11BE20 _Ant0_6715



11BE20 _Ant1_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_6855



11BE20 _Ant1_6855



11BE20 _Ant0_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant1_6875



11BE20 _Ant0_7015



11BE20 _Ant1_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20 _Ant0_7115



11BE20 _Ant1_7115



11BE40 _Ant0_5965

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant1_5965



11BE40 _Ant0_6165



11BE40 _Ant1_6165

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6405



11BE40 _Ant1_6405



11BE40 _Ant0_6445

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant1_6445



11BE40 _Ant0_6485



11BE40 _Ant1_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6525



11BE40 _Ant1_6525



11BE40 _Ant0_6565

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant1_6565



11BE40 _Ant0_6725



11BE40 _Ant1_6725

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_6845



11BE40 _Ant1_6845



11BE40 _Ant0_6885

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant1_6885



11BE40 _Ant0_7005



11BE40 _Ant1_7005

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40 _Ant0_7085



11BE40 _Ant1_7085



11BE80 _Ant0_5985

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant1_5985



11BE80 _Ant0_6145



11BE80 _Ant1_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant0_6385



11BE80 _Ant1_6385



11BE80 _Ant0_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant1_6465



11BE80 _Ant0_6545



11BE80 _Ant1_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant0_6705



11BE80 _Ant1_6705



11BE80 _Ant0_6785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant1_6785



11BE80 _Ant0_6865



11BE80 _Ant1_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80 _Ant0_6945



11BE80 _Ant1_6945



11BE80 _Ant0_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.